3 Steps to Reboot HIBOY S2 E-scooter



Loose the 4 screws by a proper hex wrench

Pull out and seperate the connector, wait 5 seconds

Connect the connector properly, and tighten the 4 screws back